



RISK ASSESSMENT[®]

Commercial Real Estate Inspectors

3266 Kirkham Drive
Glendale CA 91202
818.957.4654

This is an assessment of the five major systems - Plumbing, Electrical, Heating and Air Conditioning, Structure and Roofing along with an assessment of any other current deferred maintenance issues for the site.

This assessment will cover three aspects of these systems per industry standards, namely:

1. Expected useful life left in each system.
2. Maintenance/Repairs that are needed immediately for each system.
3. Total costs that are expected over the next five years for each system.

Note: The cost estimates are industry standards per the *R.S. Means - 2007 Building Construction Cost Data 20th Annual Western Edition* along with review and consultation with local contractors.

Although care and thought have gone into this assessment there are many variables that can cause the actual prices to differ greatly, such as: local building ordinances, requirements, specifications and details, local demand for labor, materials, etc.

No implied warrantee is given.

No cosmetic concerns have been addressed in these estimates.

No Routine Maintenance concerns have been addressed in these estimates below \$1000.

ADDRESS: Cerritos, CA

CLIENT: TFP Investments

1 Apr 2008

PLUMBING:

<p>1. The expected useful life left in the Plumbing System:</p> <p>The Expected Useful Life left in the system is, 30 - 50 years</p> <p>2. What Maintenance/Repairs are needed immediately for the Plumbing System:</p> <p>Ensure the sprinkler system has had proper inspections.</p> <p>Replace the water heater and properly strap it.</p> <p>It is advised to have a Camera review of the Waste lines by a qualified plumbing specialist. Due to these being mostly underground this is the only way to determine the true condition.</p> <p>3. What costs are expected over the next five years for the Plumbing System:</p> <p>\$500 plus routine maintenance</p>	<p>TOTAL:</p> <p>\$500 now - then</p> <p>Routine Maintenance</p>
---	---

ELECTRICAL:

<p>1. What is the expected useful life left in the Electrical System:</p> <p>The expected useful life of the electrical system is: approx. 30 - 50 years</p> <p>2. What Maintenance/Repairs are needed immediately for the Electrical System:</p> <p>The system appeared to be in serviceable condition at the time of the inspection and other than routine maintenance no immediate significant deficiencies or repairs were observed to be needed.</p>	
---	--

<p>3. What costs are expected over the next five years for the Electrical System:</p> <p>The electrical system appears to be Serviceable and no major expenses are anticipated for the next five years other than minor repairs and routine maintenance</p>	<p>TOTAL:</p> <p>Routine Maintenance</p>
---	--

HEATING AND COOLING:

<p>1. What is the expected useful life left in the Heating and Air Conditioning System:</p> <p>The typical life for roof mounted units such as these is approx. 15-17 years.</p> <p>Four of the units are well past this expected useful life. One unit is approx. 16 years old. One unit is approx. 3 years old.</p> <p>2. What Maintenance/Repairs are needed immediately for the Heating and Air Conditioning system:</p> <p>It is advised to have each unit fully serviced at this time which will typically cost approx. \$100 - \$150 per individual unit.</p> <p>3. What costs are expected over the next five years for the Heating and Air Conditioning System:</p> <p>Within the next five years significant maintenance, repairs and/or replacements will most likely be needed to five of the six units per industry standards due to age. Replacement cost for each is approx. \$5,000 - \$7,000 at todays costs.</p>	<p>TOTAL:</p> <p>\$25,000 - \$35,000</p>
--	--

ROOF:

<p>1. What is the expected useful life left in the Roofing System:</p> <p>It appears that the roof has approx. 5 - 10 years of expected useful life left in it if it is properly maintained.</p> <p>2. What Maintenance/Repairs are needed immediately for the Roofing System:</p> <p>The roof is in need of some repairs and maintenance at this time. During this review by a qualified roofer other repairs may become apparent but are not anticipated with this estimate.</p> <p>3. What costs are expected over the next five years for the Roofing System:</p> <p>It appears that the roofing system will require Routine Maintenance Only for the next five years after the above maintenance has been completed</p>	<p>TOTAL:</p> <p>Routine Maintenance</p>
--	--

STRUCTURE:

<p>1. What is the expected useful life left in the Structural System:</p> <p>It appears that the expected useful life is, 20 - 30 years</p> <p>2. What Maintenance/Repairs are needed immediately for the Structural System:</p> <p>No significant repairs at this time other than routine maintenance.</p> <p>3. What costs are expected over the next five years for the Structural System:</p> <p>No significant costs are anticipated in the next five years to the Structure</p>	<p>TOTAL:</p> <p>Routine Maintenance</p>
---	--

GENERAL MAINTENANCE & REPAIRS:

<p>1. What is the expected useful life left in the Site:</p> <p>The expected useful life left in the site is, approx. 20 - 30 years with routine maintenance.</p> <p>2. What Maintenance/Repairs are needed immediately currently for the Site:</p> <p>It is advised to have the asphalt parking areas resealed and restripped at this time.</p> <p>3. What costs are expected over the next five years for the Site:</p> <p>\$1500 - \$2500</p>	<p>TOTAL:</p> <p>\$3500 - \$4500</p>
--	--

<p>TOTAL COMBINED ESTIMATED EXPENSES:</p> <p>Further review is advised at this time by qualified specialists to determine the full scope of work. These estimates should be used as guidelines only.</p>	<p>TOTAL:</p> <p>\$30,000 - \$45,000</p>
---	--

RISK Assessment[®] Report

April 01, 2008.



TFP Investments

Cerritos, CA

Inspector - Bob Pace & Shaun Fabos
Confidential and Proprietary

3266 Kirkham Dr., Glendale CA 91206
818.957.4654 www.creillc.com

SITE PHOTO



TFP Investments Cerritos, CA.

INSPECTION CONDITIONS

CLIENT & SITE INFORMATION:

DATE OF INSPECTION: April 01, 2008.
TIME OF INSPECTION: 10:00 AM.
CLIENT NAME: TFP Investments.
ADDRESS: Cerritos, CA.
INSPECTOR: Bob Pace & Shaun Fabos.

CLIMATIC CONDITIONS:

WEATHER: Overcast.
TEMPERATURE: 60's.

BUILDING CHARACTERISTICS:

BUILDING TYPE: This building is a combination of office space along with warehouse space.
STORIES: Two.

UTILITY SERVICES:

UTILITIES STATUS: The utilities were on.

OTHER INFORMATION:

BUILDING OCCUPIED: Yes.
CLIENT PRESENT: No.
COMMENTS: It is important to understand that though the Inspection Agreement in the back of the report may not have been signed by the client it is understood that use of this Report implies the acceptance of the agreement and all its terms by the client.

PAYMENT INFORMATION:

TOTAL FEE: \$XXXX.

PAID BY: Check.

DEFINITIONS AND STANDARDS

TERMS OF THE INSPECTION:

SERVICEABLE: It is the inspectors opinion that this item is doing the job for which it was intended and exhibits normal wear and tear.

NEEDS ATTENTION: It is the inspectors opinion that this item is in need of further investigation and/or repairs or appears to be at the end of its expected useful life. The inspector has made the client aware of this situation by calling it "needs attention" in the report and it is then the clients responsibility to take appropriate action concerning the situation with the appropriate professional in a timely manner.

NOT ACCEPTABLE: It is the inspectors opinion that this item is either in need of immediate repairs or is a safety hazard due to adverse conditions. Also the item may be in such a state of disrepair that significant repairs or replacement is strongly advised.

The inspector has made the client aware of this situation by calling it "not acceptable" and it is then the clients responsibility to take appropriate action concerning the situation with the appropriate professional in a timely manner.

STANDARDS:

A. The report conforms to the Commercial Standards of Practice of the California Real Estate Inspection Association and the Business and Professions Code which defines a commercial real estate inspection as: The inspection to be performed consists of non-intrusive visual observations to survey the readily accessible, easily visible material components, systems and equipment of the building. The inspection is designed to identify material physical deficiencies in the buildings components, systems and equipment, as they exist at the time of the inspection. Unless otherwise agreed between the inspector and client, the specific systems, structures and components of a building to be examined are listed in these Commercial Standards of Practice.

B. A commercial real estate inspection report provides written documentation of material physical deficiencies discovered in the inspected building's systems and components which, in the opinion of the Inspector, are safety hazards, are not functioning properly, or appear to be at the end of their expected useful life. The report may include the Inspector's recommendations for correction or further evaluation.

The term **material physical deficiencies** means the presence of conspicuous patent defects or material deferred maintenance of the buildings material systems, components or building equipment as

observed during the inspection. **This definition specifically excludes deficiencies that may be remedied by routine maintenance.**

C. Inspections performed in accordance with these Standards of Practice are not technically exhaustive and shall apply to the primary building and its associated primary parking structure.

PLUMBING SYSTEM

While some plumbing observation may be code related, this inspection does not determine if the system complies with code. Supply and waste lines are inspected only where they are accessible and while operating accessible fixtures and drains. Performance of the water flow can vary during different times of the day and performance of the drain during actual usage is undetermined. Drain blockage is common in vacant property.. It is advised to have any underground drain lines examined by a specialist with a camera to determine their actual condition. The following are not included; inaccessible supply or waste lines, leaks in inaccessible areas such as walls, underground or the crawl space, the interior of pipes for mineral or corrosive clogging, water hammering, solar equipment or water temperature, and the condition of shower pans or if a shower will leak when used. No water testing of any type is performed. The type of copper, whether it is M, L, or K, is not part of this inspection and will not be determined. The gas system is not tested for leaks and any underground or hidden gas lines are specifically excluded from this report. Determining the operation of sewer ejection systems is excluded from this inspection and it should be examined by a specialist. The angle stops under sinks and other plumbing valves, such as the main shut off valve, are not turned or tested.

MAIN WATER SUPPLY LINE:

MAIN WATER LINE
MATERIAL:

Copper piping is viewed by the building and appears to be the main supply line for the building. The majority of the main line runs underground from the street to the building, this appears to be the main water line.

MAIN WATER SHUT
OFF LOCATION:



In the front of the building.

CONDITION:

Serviceable.

WATER SUPPLY PRESSURE REGULATOR:

CONDITION: Needs Attention, no pressure regulator was observed at the main line where it enters the structure. Sometimes they are installed in other areas and it is advised to check with a professional to determine if there is one on the system or not.

WATER VOLUME AT
FIXTURES: Serviceable.

INTERIOR WATER SUPPLY LINES:

WATER SUPPLY
PIPING MATERIAL: The interior piping that supplies the water throughout the building is made of copper where viewed.

CONDITION: Serviceable where viewed.

WASTE LINES:

WASTE LINE
MATERIAL: The piping that takes the waste water to the sewer system is a combination of different materials where visible.

CONDITION: A representative examination of the visible waste lines found that those examined were working properly.

WASTE LINE
COMMENTS: **The waste lines are under the slab and in the walls of the building. They are, for the most part, not visible and were not inspected. Due to these being under the slab or under the earth it is only possible to inspect these with specialty camera equipment by a qualified plumber specialist. It is advised to have this done at this time.**

GAS SYSTEM:

SEISMIC GAS SHUT
OFF VALVE: There is no automatic seismic gas shut-off valve on the main gas line. This may not need to be installed in this municipality at the time of sale but is recommended for safety.

**GAS METER
LOCATION:**



The gas meter was located on the right side of the building near the front.

CONDITION:

It is advised to have the gas provider inspect the gas system to determine its condition and check all the gas appliances and fixtures. This is usually a free service.

WATER HEATER:

LOCATION:



Over the bathroom near the roof access ladder.

LOCATION
CONDITION:

Serviceable.

FUEL:

Electric.


SIZE:

15 gallons.

AGE:

17 years old. Water heaters have an expected life of 8 - 12 years.

CONDITION:



Needs Attention, there is scorching on the exterior of the water heater. The reason this occurred is not known as it was not doing it during this inspection but it has occurred in the past. Also the water heater is very old and past its expected life span. It may need to be replaced soon.

WATER HEATER
STRAPPING AND
SUPPORT:

Needs Attention, the water heater needs to be properly strapped for earthquake safety in accordance with standards established by state regulations.

TEMPERATURE/
PRESSURE RELIEF
VALVE:

Serviceable.

COMMENTS:

The adequacy or efficiency of the hot water heater cannot be determined in a limited time visual inspection. It is not known how hot the water will get or how long it will last and this is many times a matter of personal preference.

WATER HEATER:

COMMENTS:

The adequacy or efficiency of the hot water heater cannot be determined in a limited time visual inspection. It is not known how hot the water will get or how long it will last and this is many times a matter of personal preference.

WATER HEATER:

COMMENTS:

The adequacy or efficiency of the hot water heater cannot be determined in a limited time visual inspection. It is not known how hot the water will get or how long it will last and this is many times a matter of personal preference.

PLUMBING COMMENTS:

WASTE LINE
COMMENTS:

The waste lines that go out to the sewer system are to a large degree installed underground and are not visible. Their condition is unknown. The only way to determine what is going on with them is to have them checked out with a camera by a specialist to determine their true condition and any needed repairs.

GENERAL
COMMENTS:

The majority of the water supply pipes, waste lines and gas lines are underground, in walls or installed in concealed parts of the structure and thus are not visible. Their condition cannot be determined and no representation is made as to their status.

ELECTRICAL SYSTEM

Electrical features are operated with normal controls. The general wiring, switches, outlets and fixtures are randomly checked in accessible areas. Wiring in the main box is inspected by removing the cover if accessible. While some observations may be code related, this inspection does not determine if the system complies with code. The inspection does not determine electrical capacity, determining over current capacity for any item including appliances, comparing circuit breaker capacity to installed appliance listings, interior or exterior low voltage wiring or fixtures, telephone, security, intercom, stereo, cable or satellite TV, remote controls or timers. The exterior lighting, landscape lighting or any lighting outside the footprint of the building is not inspected. Light bulbs are not removed or changed during an inspection. This inspection does not certify or warrant the system to be free of risk of fire, electrocution or personal injury or death.

MAIN ELECTRICAL SERVICE:

TYPE OF ELECTRICAL SERVICE:



400 Amp. This is a 3 Phase 4 Wire system. The electricity is supplied by an underground line.

MAIN PANEL LOCATION:

At the right rear corner of the building.

MAIN PANEL AMPERAGE:

Service Amperage - 400 amp.

TYPE OF CIRCUIT
PROTECTION DEVICE:



The shut off device is a disconnect lever.

MAIN PANEL
CONDITION:

Serviceable.

MAIN PANEL CIRCUIT
BREAKERS:

Serviceable.

GROUNDING SYSTEM COMMENTS:

COMMENTS:

The connection of the grounding wires to the grounding system is not visible. It should be connected to a grounding rod and/or the cold water piping system but in many cases these connections are not observable and are covered over within the building.

ELECTRICAL SUBPANELS:

SUBPANEL
LOCATION:



There is an electrical subpanel in more than one location such as at the rear of the office space.

SUBPANEL
CONDITION:



Serviceable.

INTERIOR ELECTRICAL WIRING:

TYPE OF WIRING

CONDUIT: The conduit that carries the wiring is a combination of different types.

WIRING CONDITION: Serviceable however the view is limited.

OUTLETS:

CONDITION: A representative sampling of outlets were tested and those that were checked were found to be in working order.

SWITCHES:

CONDITION: A representative sampling of switches were checked and those that were tested were found to be in working order.

FIXTURES:

CONDITION: Serviceable.

EXTERIOR ELECTRICAL:

CONDITION: The exterior lighting outside the building and on the grounds is not part of the inspection.

FIRE SUPPRESSION & SAFETY SYSTEMS

FIRE SUPPRESSION SYSTEMS:



There is an interior fire suppression system in the unit. This is not tested as part of a general visual property inspection.

FIRE SAFETY SYSTEMS:

This type of building is required to have certain fire safety items. These are items such as exit signs and fire extinguishers. It is advised to check with the local Fire Marshall to determine if this building meets current fire safety regulations.

ELECTRICAL COMMENTS:

ELECTRICAL WIRING COMMENTS:

Low voltage lighting and wiring is excluded from a standard property inspection including outdoor lights, phone lines, security systems and speaker systems. Regular voltage exterior lighting is also excluded.

ELECTRICAL COMMENTS:

The wiring is enclosed within the walls and ceilings and other parts of the structure. It is not visible and its condition cannot be fully determined. No representation is made as to its status.

HEATING AND COOLING SYSTEM

While some observations may be code related, this inspection does not determine if the system complies with code. Weather permitting the systems are operated with normal controls. In order not to damage the system, the air conditioners are not activated if the outdoor temperature is below 65 degrees. Gas furnaces are not checked for carbon monoxide leakage or fire risks. There are carbon monoxide and fire detection devices which can be purchased and installed, which we recommend. Air ducts and registers are randomly checked for air flow. Heat exchangers are specifically excluded from the inspection. They are visually obstructed by the design of the system and a complete inspection requires special tools and disassembly, which is beyond the scope of the inspection. The following items are beyond the scope of the inspection; balance of the air flow, capacity or velocity of the air flow, humidifiers, air duct cleanliness, the ability of the system to heat or cool evenly, the presence of toxic or hazardous material or asbestos, system refrigerant levels, cooling or heating capacity to determine if its sufficient for the building, electronic air filters, solar equipment, programmable thermostats and determining the remaining life of the system. Window A/C's are not built in units and therefore not inspected.

All the units are on the roofing. All units supply the office spaces in the front of the building.

There are a total of 6 units for the building.

HEATING AND COOLING SYSTEM:

The units service the office areas.

HEATING AND COOLING SYSTEMS:

LOCATION: The heating and cooling units are located on the roof.

LOCATION
CONDITION:



Typical units on blocks.

Needs Attention, Three of the 6 units are sitting on wooden blocks. This is not a reliable method regarding moisture intrusion. It is advised to have platforms with metal caps installed to help ensure a leak free condition.

SYSTEM TYPE: The heating and cooling systems are located on the roof and are the type that the gas heating furnace and electric cooling system are packaged in one container and serve both functions.

CONDITION: **Needs Attention:**
Per industry standards the expected useful life of this type of unit is approx. 15 - 17 years depending on the frequency and quality of maintenance. Quarterly maintenance is recommended for optimum operation and longest lasting life.

Four of the six units are aged and worn. They appear to be original from 1984 and well past their expected useful life.

One unit is 16 years old and at the end of it's expected useful life.

One unit is approx. 3 years old.

DUCTING: **Needs Attention, the ducting in the spaces over the offices is aged and worn and no longer appears to be well sealed.**

GENERAL COMMENTS: **It is advised to have all the units serviced and cleaned at this time to ensure safe and properly functioning systems. It is beyond the scope of this general visual inspection to inspect the inner workings of the systems. This can and should be done by a licensed Heating and Cooling specialist at this time.**

HEATING AND COOLING COMMENTS:

COMMENTS: Per the California Energy Commission, "Beginning October 1, 2005, Title 24 of the Building Energy Efficiency Standards requires that ducts be tested for leaks when a central air conditioner or furnace is installed or replaced. Ducts that leak 15% or more must be repaired"

A property inspection will not be able to determine if this air loss exceeds the maximum allowed of 15%. This test can only be done by a qualified technician and is beyond the scope of this inspection. It is advised to consult with a qualified specialist on this matter as the examination may determine that repairs or replacement of the ducting system is required.

ROOF SYSTEM

The report is not intended to be conclusive regarding the life span of the roofing system, if it is leak free or how long it will remain leak free in the future. The inspection and report are based on visible and apparent condition at the time of the inspection. The inspection does not address manufacturing defects, fastener appropriateness, if the roof was installed per code, if flashing is present in all locations or the numbers of layers present. Unless a rain has fallen just prior to the inspection, it is not possible to determine if active leakage is occurring. Not all attic areas are readily accessible for inspection. Tile roofs and steeply pitched roofs are not safe to walk on and access is limited on them. Conclusions made by the inspector do not constitute a warranty, guaranty, or policy of insurance. All roofs require periodic maintenance to achieve typical life spans and should be inspected annually. Expect to make minor repairs to any roof.


While it is possible some prior repairs and leaks may be reported, it is not the intention of the inspection to identify and report all prior repairs and conditions. It is recommended to refer to the seller and sellers disclosure about the presence of any roof leaks or prior repairs. Also it should be noted that all gutters have rust and have a limited life span before they need to be replaced.

ROOF OVERVIEW:



ATTIC:

TYPE OF ROOF
FRAMING:



The roof is supported by structural beams and cross supports.

ROOF FRAMING
CONDITION:

Serviceable.

ACCESS TO ROOF:



Access to the roof is via a ladder that is accessed inside the building.

ATTIC INSULATION:

INSULATION
CONDITION:

Serviceable overall with a few pieces of the insulation paper being torn and not in place.

ROOF:

ROOF STYLE:

The roofing system is a flat roof with a low pitch.

TYPE OF ROOFING
MATERIAL LOW

SLOPE ROOF:

The roofing material on the low sloped roof is rolled composition roofing.

ROOF ACCESS:

The roof was walked on to inspect it.

**ROOF COVERING
STATUS:**



Flat area left and patched area right

The roof appeared generally serviceable however:

Needs Attention, on the low sloped roof, The roof does not have the recommended 1/4" per foot slope in it to allow water to run off properly during rains in all areas. It is advised to increase the slope on the roof to the recommended 1/4" per foot in those areas however this may not be practical do to expense. Review by a roofer at this time is advised. It will be very important that the roof has regular maintenance to help ensure a a leak free condition. This is noted mainly in the center of the roof.

Also on the low sloped roof, It is noted there are areas of the roof that have had patching and or repairs done to them at the right front corner. This is usually an indication that there have been leaks and past issues. It is advised to have full disclosure by the seller as to the history of any roof leaks.



Debris around drains.



Debris left front and torn side wall paper

EXPOSED FLASHINGS:

CONDITION: Needs Attention, the mastic is cracked in areas and is not reliable to ensure a watertight seal.

SKYLIGHTS:

CONDITION:



Typical skylight.

Serviceable.

SCUPPER, GUTTERS, DOWNSPOUTS & ROOF DRAINAGE:

SCUPPER OR GUTTER
CONDITION:

Needs Attention, there are areas where the drainage system has excess debris and needs to be cleaned out. This includes all accumulated roof debris on the roof itself. See pictures above.

ROOF COMMENTS:

COMMENTS:

The roof is in need of maintenance at this time. It is advised to have a roofer examine the entire roofing and drainage system and make any needed repairs or do any maintenance functions needed to help ensure a leak free condition at this time.

The roofing has been inspected at a time when it was not raining. Since one of the purposes of any roofing system is to repel water this could not be observed and verified as occurring in all cases. Therefore the roof system has not been tested under wet conditions and how it performs in these condition is unknown. No warranty is made that the system will not leak when it is under a wet condition.

It is important for all roofs to have regular maintenance, including cleaning out any and all drainlines or gutters and ensuring all the penetrations are properly sealed.

FOUNDATION SYSTEM

Structural comments are of the conditions observed at the time of the inspection and are the opinion of the inspector and not fact. If further information or facts are needed, they can be obtained through a structural engineer or foundation expert. The inspection does not determine the potential of the structure to experience future problems, geological conditions or the potential of the underlying soils to experience movement or water flow or whether the soil is stable. If any form of prior structural movement is reported you should expect future movements and possible repairs.

The inspection does not calculate crawl space ventilation capacities, deck and balcony capacity, retaining wall conditions, construction material type, quality or capacity. It does not address the existence of prior repairs, the potential of future repairs, failure analysis, documentation of all possible movement or cracks in floor slabs covered by floor furnishings. It is typical for concrete floor slabs to have some hairline cracks as a result of the normal drying process of the concrete plus the stress occurring by settlement and seismic activity. Crawl spaces are observed in a cursory fashion and wood probing is not done and wood damage, dryrot and termites are not part of this inspection but part of the structural pest control operators report.

FOUNDATION:

SLAB ON GRADE:

This building is on a monolithic slab of concrete. There were no observable signs of significant settlement or deflection in the slab from observing the finish flooring. It appears to be performing its function of supporting the structure however the the actual slab itself was not seen and it may appear different once the finish flooring is removed. By the nature of slab construction the structure would be bolted to this concrete slab.

SLAB ON GRADE COMMENTS:



Typical slab flooring in warehouse.

There are cracks in the slab that appear to be typical for the age and style of construction. However if you need a more detailed evaluation it is advisable to contact a structural engineer or a foundation specialist.

EXTERIOR

The exterior is viewed in a cursory fashion. Areas of the exterior that are hidden from view by vegetation or stored items cannot be judged and are not a part of this inspection. Minor cracks are typical in many exterior wall coverings and most do not represent a structural problem. Peeling and cracking exterior paint on windows, doors and trim allow water to enter and cause damage and deterioration. It is important to keep these exterior surfaces properly painted and/or sealed. Many times chimneys have hidden undisclosed cracks that cannot be seen. A chimney specialist inspector should be employed to determine the true condition of the structure of any chimney as it is beyond the scope of this inspection to determine damage to chimneys. All exterior grades should allow for surface and roof water to flow away from the foundation and exterior walls.

EXTERIOR COVERING OF THE BUILDING:

MATERIAL: Concrete Tilt Up construction.

CONDITION:



Right side wall area.

Serviceable however there is typical cracking in the exterior walls.

ADDITIONAL NOTES:



The water from the sprinklers appear to hit the exteriors of the building, this can cause deterioration and/or damage and moisture intrusion, water should be directed away from the structure.

EXTERIOR WINDOW SURFACES:

MATERIAL: The exterior window surfaces are metal.

CONDITION: Serviceable overall however some weathering is occurring such as in the front from the sprinklers.

EXTERIOR DOOR SURFACES:

MATERIAL: The exterior door surfaces are metal.

CONDITION:



Serviceable overall.

EXTERIOR COMMENTS:

COMMENTS: This inspection is not a structural pest control inspection, otherwise known as a termite inspection. The "termite" inspection also covers such things as dryrot and wood damage and deterioration as well as wood destroying organisms. Any and all of these items need to be examined and any repairs completed by the "termite" company in a timely manner and they usually have a guarantee on their work. Please refer to the structural pest control report for any information concerning them

This is not a mold or fungus inspection, it is therefore advised to have a mold specialist examine the property and structure and do a complete inspection to determine the presence or not of any mold that may affect the health or safety of the occupants.

GROUNDS

This inspection is not intended to address or include any geological conditions or site stability information. For information concerning these conditions, a geo-technical engineer should be consulted. Proper grading is important to keep water away from the foundation. If it is not raining during the inspection the course of water flowing toward the structure or off the site cannot be observed. The soil should slope away from the structure to prevent problems caused by excess water not flowing away properly. Gutter discharge should be directed away from the foundation for the same reason. Out buildings, such as storage sheds, on the property are excluded from the inspection. Fire pits, a B.B.Q. and other similar items are not inspected nor is the gas to them tested or lit.

This inspection is visual in nature and does not attempt to determine drainage performance of the site or the condition of any underground piping, including municipal water and sewer service piping or septic systems. Landscape lighting, sprinklers and their timers are not part of a general property inspection. The inspection report does not include the identification of the property boundaries.

DRIVEWAY:

CONDITION:



Serviceable.

WALKWAYS:

CONDITION:

Serviceable.

FRONT ENTRY:

CONDITION:



Serviceable.

LANDSCAPING:

CONDITION:

The grounds on the property have generally been maintained.

DRAINAGE:

SITE:

Flat site.

DRAINAGE
CONDITION:

There were no observable defects in the grading and drainage within six feet of the building.

COMMENTS:

Determining the adequacy of the grounds to shed water and prevent moisture intrusion into the structure is beyond the scope of the inspection. It is advised to obtain the history of any drainage problems and monitor the site regarding water run-off and drainage in general.

This inspection does not address drainage issues further than 6 feet from the building. Additionally drainage systems that are not visible such as underground systems are not evaluated or inspected. If more information is required it is advised to consult with a drainage specialist.

INSPECTION LIMITATIONS

SPECIFIC EXCLUSIONS AND LIMITATIONS:

OUR GOAL:

Our Goal is to enlighten you as to the condition of the property by identifying material defects that would significantly affect the property and therefore your decisions concerning it. We strive to add significantly to your knowledge of the building. **Thus the goal is not to identify every defect concerning the property but focus upon the material defects and thereby put you in a much better position to make an informed decision.**

GENERALIST VS. SPECIALIST

A property inspector is a generalist and the inspection is conducted along generalist guidelines as listed above. The generalist job is to note material defects in the property he is inspecting. When he observes and finds one or more problems in a system of the property that affects its performance he may then refer the entire system over to a specialist in that field for a further detailed investigation. The specialist is expected to conduct a more detailed examination on that system from his specialist sphere of knowledge and training to determine all the problems with the system and the related costs of repairs. The specialist is inspecting from a depth of knowledge and experience that the generalist does not have.

REPRESENTATIVE SAMPLING:

The building has many identical components such as windows, electrical outlets, etc. We inspect a representative sampling of these only. We do not move any furniture or personal belongings. This means that some deficiencies which were there may go unnoted or there may be items which are impossible to anticipate. We suggest that you plan for unforeseen repairs. This is part of property ownership as all buildings will have some of these repairs as well as normally occurring maintenance.

USE OF THE REPORT:

The inspection report does not constitute a warranty, insurance policy or guarantee of any kind. It is confidential and is given solely for the use and benefit of the client and is not intended to be used for the benefit of or be relied upon by any other buyer or other third party.

PRE-INSPECTION AGREEMENT:

Terms and conditions crucial to interpretation of the report are contained in a separate pre-inspection agreement. Do not use this report without consulting the pre-inspection agreement as use of this report constitutes the acceptance of all the terms, conditions and limitations in that agreement.

MOLD, MILDEW AND FUNGI:

Mold, mildew and fungus are specifically excluded from the inspection and the report. The inspector is not qualified to note the presence or absence of mold. Mold can be a serious problem and should not be overlooked. The structure should be inspected for mold during the inspection contingency period by a specialist in this field to ensure that this hazard does not exist.

WOOD DESTROYING ORGANISMS:

Termites, dryrot, wood rot and wood destroying organisms are covered by a structural pest control operator's report. These are not part of the inspection and the inspector will not be inspecting for them. The Business and Professions Code prohibits anyone but licensed structural pest control operators from commenting on this subject.

BUILDING CODES:

This is not a building code or code compliance inspection. That is a different type of inspection performed by the local municipality, usually during construction. It is advised to obtain all available documentation such as building permits and certificates of occupancy during the inspection contingency period.

HAZARDOUS SUBSTANCES:

Identifying hazardous substances is not part of this inspection. Items such as formaldehyde, lead based paint, asbestos, toxic or flammable chemicals and environmental hazards are not tested for and are not within the scope of the inspection.

INSPECTION LIMITATIONS:

This is a limited time visual inspection. It excludes any items we cannot directly observe such as chimney interiors, furnace heat exchangers, underground piping, etc. These are specialty inspections and those inspections can be arranged using specialized equipment.

Additionally we do not inspect to see if components are installed properly. We do not have the specialized training, instruction sheets or manuals to determine if they meet manufacture's or building code requirements for installation, which can be quite varied. This is part of the specialist's inspection and any questions concerning installation would best be answered by the specialist.

CONDITION:

PARKING LOT:

DRIVEWAY:



Needs Attention, The parking areas are in need of being resealed and restripped in the front and left sides. The left side rear area is concrete and appears to be serviceable for the most part.

Per plans disclosed at the time of the inspection the right side parking spaces against the building are not part of this site but are part of the building immediately to the right as you face this building from the street.



Commercial Real Estate Inspectors

3266 Kirkham Drive
 Glendale CA 91202
 818.957.4654

INVOICE

<i>Received from</i>	<i>Date</i>
TFP Investments	April 01, 2008.

<i>Description</i>	<i>Amount</i>
Property Inspection <i>Property address:</i> Cerritos, CA <i>Inspector:</i> Bob Pace & Shaun Fabos <i>Payment Amount:</i> Terms: Cash/Check/VISA/MC/AMEX Due upon Receipt	\$XXXX
PAID IN FULL	\$XXXX

Thank you for your business!

INTERIORS

As a general rule, cosmetic deficiencies are considered normal wear and tear and are not reported. The condition of walls behind wall coverings, paneling and furnishings cannot be judged. Minor cracks are found on interior surfaces in all buildings and are typically cosmetic in nature. The condition of floors underneath carpet, furniture and other coverings cannot be determined and is specifically excluded from the inspection and report. Only the general condition of visible portions of floors is included in this inspection. Window and door security bars are not tested or operated. Determining the condition of insulated glass is not always possible due to weather, temperature and lighting conditions. All fireplaces should be cleaned and inspected on a regular basis to make sure that it is a safe and structurally sound system. It is beyond the scope of this inspection to determine and cracking or damage to the chimney or its flue. This can only be determined by a chimney expert.


COMMON AREAS:

ENTRY:

This building has office space in the front and warehouse space in the rear. There are 4 restrooms in the building. Two in the office spaces and two in the warehouse area. There is a kitchen and 4 warehouse doors in the rear warehouse area.


The building is made up of concrete/drywall walls, carpet/concrete floors and open/drop ceiling..

LOBBY



Serviceable.

HALLS:



Serviceable.

**MAIN ENTRY DOOR
CONDITION:**

Serviceable.


**EXTERIOR DOORS
CONDITION:**

Serviceable, with typical wear.

**INTERIOR DOORS
CONDITION:**

Serviceable, with typical wear.

WINDOW CONDITION:



Moisture stains

Needs Attention: There are moisture stains at the base of the window in the conference room in the office area near the front door.

**FLOORING
CONDITION:**



Pictures of worn linoleum and carpet

Needs Attention, there are areas of worn linoleum and the worn and stained carpet.

INTERIOR COMMENTS:

COMMENTS:

This is a general visual inspection, there was no destructive or intrusion testing performed. The intention of this report is to inform the client of the overall condition of the property and the material defects therein, not to itemize or list all the individual flaws.

**GENERAL
COMMENTS:**

The interior of the building has items blocking the view in some areas and therefore access to parts of the property.

ADDITIONAL NOTES:

It is typical when a building is remodeled or repairs are undertaken that additional problems surface that were not noted on the inspection report. This is to be expected as walls, floors and ceilings are opened up during the work to reveal areas that were not accessible during the inspection. Any remodeling work undertaken on a property should be expected to reveal some of these problems and it is recommended that additional sums be set aside for this purpose.

During this inspection there may be items discovered that require further inspection and/or subsequent repairs. Where further inspection by a specialty trade is advised, this is meant to be done during the inspection period, prior to any contingency expiring and certainly prior to the close of escrow if this is a sale. The whole intent of this procedure being to fully discover the extent of the

repairs needed and the associated costs.

This is not a mold or fungus inspection, it is advised to have a mold specialist examine the property and structure and do a complete inspection to determine the presence or absence of any mold that may affect the health or safety of the occupants.

UNIT:



Front Office Area.

INTERIORS:

Needs Attention:

CEILING: There are areas of moisture stains on the ceiling, There are areas of damage to the ceiling.

FLOOR: The carpet has areas of wear, staining. There are multiple areas of damage linoleum flooring.



Picture of the moisture stains and damage to the ceiling.

KITCHEN:



Kitchen, wet below

Needs Attention: While generally functional there are areas of wear and deterioration.

COUNTERS: The counter tops have areas of wear,

CABINETS: The cabinet surfaces are worn
The shelf below the sink has moisture deterioration.

FAUCET: The faucet drips continuously, and needs repair. There is no hot water at the sink

BATH 1:



Mens Restroom

Needs Attention: While generally functioning there are areas with noticeable wear that could use servicing and maintenance.

WALLS / CEILING: There are areas of damage that will need repair

FLOOR: The floor is worn and damaged in areas. There is moisture staining and damage to the floor covering and it may need repair / replacement.

WINDOW / VENTING: The bath vent fan is not working correctly,

BATH 2:



Womens Restroom

Needs Attention: While generally functioning there are areas with noticeable wear that could use servicing and maintenance.

FLOOR: The floor is worn and damaged in areas.

TOILET: The toilet leaks at the base of the handle.

UNIT:



Warehouse area

INTERIORS:

Needs Attention: There is typical wear to the unit,

CEILING: There are multiple areas of ceiling insulation falling from the ceiling such as in the rear.

FLOOR: There are damage areas of the flooring.

WALLS: There are areas of damage to the walls

It is noted that multiple loading dock did not function at the time of inspection.



Pictures of the ceiling insulation falling down from the ceiling.



Pictures of the wall damage in the warehouse area.

BATH 1:

Womens Restroom

Needs Attention: While generally functioning there are areas with noticeable wear that could use servicing and maintenance.

BATH 2:



Mens Restroom

Needs Attention: While generally functioning there are areas with noticeable wear that could use servicing and maintenance.

INTERIOR COMMENTS:

COMMENTS:

This is a general visual inspection, there was no destructive or intrusion testing performed. The intention of this report is to inform the client of the overall condition of the property and the material defects therein, not to itemize or list all the individual flaws.

GENERAL
COMMENTS:

The interior of the building has personal items and furniture blocking the view and therefore access to parts of the property.

This is not a mold or fungus inspection, it is advised to have a mold specialist examine the property and structure and do a complete inspection to determine the presence or not of any mold that may affect the health or safety of the occupants.

During this inspection there may be items discovered that require further inspection and/or subsequent repairs. Where further inspection by a specialty trade is advised, this is meant to be done during the inspection period, prior to the contingency expiring and certainly prior to the close of escrow. The whole intent of this procedure being to fully discover the extent of the repairs needed and the associated costs.